

2512 W. INTERSTATE 44 SERVICE ROAD-OKLAHOMA CITY, OK 73112 VOICE: 405.722.5800 FAX: 405.602.3863 www.preconstructionservices.com

Initial Cost Report

August 23, 2018

Mr. R. Greg Andrews Robinson Renaissance, 11th Floor 119 N. Robinson Oklahoma City, OK 73106

Re: Smith Residence – 314 8th Street– Cushing, OK

Dear Mr. Andrews,

On April 20, 2018, I made a site visit along with yourself, we met and made a walk-through to tour the issues to the Smith Residence in Cushing, Oklahoma. Also present was Mr. Steve Ford. PE, PHD, representing ZFI Engineering, Inc. and the opposing Attorney, Mr. Adam Engel of Mansell, Engel and Cole Law Firm, to observe and take photographs of the damage issues. During the site visit, I made observations and familiarized myself with the site.

Site Observations:

During my site visit, I took 67 photos (photos can be supplied upon request). I started my observations with the direction of Mr. Ford of ZFI Inc. Mr. Ford had difficulties distinguishing between an aged structure, deferred maintenance and possible earthquake damage. It was difficult to see and plaster cracking in the walls, since the walls were incapsulated with plywood paneling. Most of the ceilings were incapsulated with acoustical tile, making it difficult as well, to observe any ceiling plaster cracking.

The carpet was pulled back, to observe the cracking in the northeast bedroom concrete floor. Steve Ford recommended digging from the outside, for the depth of the footing. Both of us excavated in two locations: 1) The north wall of the Northeast bedroom



addition and 2) The east wall of the living room. The bedroom appeared to have no foundation footing, and the living room foundation consisted of masonry stone rubble, approximately 10" below the wood plate. Mr. Ford looked into the attic through the kitchen ceiling access scuttle and under the house, through the master bedroom closet floor access.

Based on Mr. Ford's findings, the earthquake damage he could visibly observe, was four (4) to six (6) brick column supports, supporting the floor structure under the house, were partially dislodged. I observed 171 photos Mr. Ford supplied to me from our site visit on April 20th. Since Mr. Ford was the only person from our site visit who crawled under the house, I reviewed the photos he produced showing the dislodged brick pilasters.

Estimate Methodology:

Before attending the site visit, I reviewed the Rimkus Consulting Group Inc. – Ms. Lisa M. Holliday, PE, PHD Report, to familiarize myself with the background of issues of the structural failures. On page 3 of her Report, Ms. Holliday mentioned that the Smith's stated "the front door would not close, and they replaced it." Other than the door, I could not find any other items from her report for me to estimate.

Mr. Ford relayed to me the issues with the brick pilasters under the house. I discussed with Mr. Ford, the difficulties of accessing to repair the brick pilasters. Mr. Ford suggested I need to estimate the cost of accessing the floor by pulling back the carpet and cutting two holes in the wood floor system either side of the north/south running floor beam, for personnel access, materials and equipment. These access points would most likely be in the living room and one of the bedrooms.

Once the access is made, it would be necessary to shore the structure and then remove and clean the bricks for proper replacement with new mortar. The estimate also includes the subfloor repair, the patching of hardwood flooring and staining finish. The carpet would be relayed as well.

It is my understanding that the goal is to perform the repairs as quickly as possible to minimize the Smith's interruption.

Documents supplied to my firm were the following:

ZFI findings as described above

Rimkus Consulting Group, Inc. Report of Findings-dated 09.18.2017

Additional work not included in the cost estimate:

- 1) Costs for Rentals, Lodging during the repairs for the Smith Residences
- 2) Costs for removal, storage, and replacement of loose furnishings.

Opinions:

The Cost Estimate provided with this Report is based on conclusions of the ZFI findings and opinion of repairs along with my own visual observations and experience.

Facts and Data:

The unit Costs are based on: Gordian - R.S. Means 2018 Residential Cost Data 37th annual edition.

Conclusion:

This is my "Initial Cost Report," and I reserve the right to further clarify/modify my estimate after review of any further analysis or any other supplemental reports, depositions or other engineering information, if provided, relating to this case after the date of this Cost Report.

Repair Estimate, as described above:

Estimate	\$8,523
Total:	\$8,523

QUALIFICATIONS + AFFILIATIONS

(See attached for breakdown.)

B.S. DEGREE ENGINEERING TECHNOLOGY-OKLAHOMA STATE UNIVERSITY 1976 A.S. DEGREE CONSTRUCTION MANAGEMENT TECHNOLOGY-OKLAHOMA STATE UNIVERSITY 1976

MECHANICAL & ELECTRICAL ESTIMATING – R.S. MEANS CERTIFIED 2000 FACILITIES ESTIMATING SEMINAR –R.S. MEANS 2000

DESIGN AND CONSTRUCTION COMMITTEE-OKLAHOMA CITY MEMORIAL 1995-1998

AMERICAN SOCIETY OF PROFESSIONAL ESTIMATORS-CPE CERTIFIED 2005

CHARTER MEMBER ASPE OKLAHOMA CITY-LANDRUN CHAPTER 80

ASPE-OKLAHOMA CITY-LANDRUN CHAPTER 80 - PRESIDENT 2008-2011,

ASPE-OKLAHOMA CITY-LANDRUN CHAPTER 80 - MEMEBERSHIP-CHAIR 2013-PRESENT

ASPE-NATIONAL INDUSTRY AWARENESS COMMITTEE-CHAIR 2011-2013

ASPE-NATIONAL MEMBERSHIP COMMITTEE-CHAIR 2013-2014

ASPE-NATIONAL AWARDS COMMITTEE-CHAIR 2014-2017

ASPE-NATIONAL CERTIFICATION COMMITTEE-CHAIR 2018-PRESENT

BILL GLASS CHAMPIONS FOR LIFE-PRISION MINISTRY TEAMATE

CENTRAL OKLAHOMA – AIA AFFILIATE MEMBERSHIP 2000-PRESENT CERT-CONSULTING ESTIMATORS ROUNDTABLE 2015-PRESENT -

CERT-CONSULTING ESTIMATORS ROUNDTABLE - NATIONAL PRESIDENT 2018-PRESENT

List of Publications authored by Witness:

EXPERT WITNESS: QUESTIONS TO ANSWER BEFOREHAND MAY/JUNE 2018 "DCD MAGAZINE" PAGE 56

PARALLEL ESTIMATES AS A MONEY-SAVING PRACTICE NOV./DEC. 2016 "DCD MAGAZINE" PAGE 10

BIM UPDATE-NATIONAL INSTITUTE OF BUILDING SCIENCES CONVENTION APRIL 2013 "ESTIMATING TODAY" PAGE 21

THE "BUZZWORDS" of BIM **APRIL 2012 "ESTIMATING TODAY" PAGE 23**

CERTIFIED BIM ESTIMATORS? MARCH 2013 "ESTIMATING TODAY" PAGE 6

MEMBER PROFILE-NATIONAL INDUSTRY AWARENESS COMMITTEE CHAIR - SOUTHWEST REPRESENTATIVE DECEMBER 2011 "ESTIMATING TODAY" PAGE 6

INDUSTRY AWARENESS – ESTIMATING & BIM OCTOBER 2011 "ESTIMATING TODAY" PAGE 9

LITIGATION COSTING PAST 4 YEARS:

ROSS WEAVER & ALEXANDRA STANKUS VS. S and D HOMES YUKON, OK

2018 FOUNDATIONS AND OKLAHOMA CITY.OK WEEP HOLE ISSUES

FOSHEE & YAFFE

DEPOSITION/SETTLED

BEST WESTERN PLUS 508 EAST MAIN ST. CUSHING, OK

2017

MARVIN LAWS, P.C. FOUNDATION ISSUES MUSTANG, OK

BIRD RESIDENCE 700 CABELLA COURT NORMAN, OK **DEPOSITION SETTLED**

OKLAHOMA COUNTY

2016 WATER ISSUES CARTCART DOOLEY OKLAHOMA CITY, OK

TIMBERLAKE CONSTRUCTION vs NN PROPERTIES CJ-2015-1312

2016 PUNCHLIST ISSUES

DENTON LAW FIRM MUSTANG, OK

WMATA-TRANSIT CENTER SILVER SPRING, MARYLAND

2016

AKIN, GUMP, STRAUSS LIFE CYCLE COSTS HAUER & FELD LLP

DEPOSITION SETTLED

DEPOSITION

2016 4900 CORONADO BRIDGE COURT HARRISON & MECKLENBERG FOUNDATION FAILURE FOUNDATION ISSUES LAW FIRM - KINGFISHER, OK EDMOND, OK SETTLED REPLACE WALKER RES. 2016 **GIVENS LAW FIRM** TUTTLE, OK TORNADO DAMAGE OKLAHOMA CITY STRATFORD v. FOOTLOCKER 2016 McAFEE & TAFT, P.C. 7307 NORTH MacARTHUR BUILDING REPLACE OKLAHOMA CITY, OK OKLAHOMA CITY **SETTLED** HAYS VS, FARMERS 2016 FRAILEY, CHAFFIN, CORDELL CLINTON, OK **REVIEW ESTIMATE** PERRYMAN & STERKEL CHICKASHA, OK FRANK LOVE RESIDENCE 2015 LOVE'S STORES NICHOLS HILLS, OK FIRE ESTIMATE **SETTLED** INS. REVIEW ROSSCO V. CHECOTAH 2014 STEIDLEY & NEAL CHECOTAH HIGH SCHOOL **ESTIMATING** TULSA, OK СНЕСОТАН, ОК. **EXCAVATION DEPOSITION/SETTLED** WALLING RESIDENCE 2014 HELMS & GREENE, LLC 3808 MANNING RD. **ESTIMATING** OKLAHOMA CITY, OK EL RENO, OK TORNADO DAMAGE 1-DEPOSITION WOMBLE RESIDENCE 2014 HELMS & GREENE, LLC 1817 GUILFORD LANE ESTIMATING OKLAHOMA CITY, OK NICHOLS HILLS, OK WATER DAMAGE GAINES vs TIMBERCRAFT HOMES 2014 ANDREW KARIME EDMOND, OK **ESTIMATING** OKLAHOMA CITY, OK **SETTLED** LECLEREC RESIDENCE 2014 WHEELER, WHEELER, 5715 HARPER CREEK TRAIL **ESTIMATING** MORGAN, FAULKNER & EDMOND, OK MASONRY/STUCCO/ **BROWN** 2-DEPOSITIONS DRYWALL/ROOFING **ARBITRATION WITNESS ISSUES** WESTERN HEIGHTS VS 2014 BROWN & BROWN, PC KB CONSTRUCTION, INC. ESTIMATING OKLAHOMA CITY CASE NO. CJ-2011-7230 ROOF REPAIR OKLAHOMA COUNTY SETTLED

Statement of Compensation in this case:

Estimating services, meetings, site visits and travel time: \$120 per hour

Depositions and Prep: \$140 per hour

Court Witness, Arbitration Witness and prep: \$150

(rates are subject to change after one year of retainment)

(PCSI uses it's proprietary software and reserves the right to protect it's own interests. The Client will have no rights to the software itself, yet the work produced in protected format, may be provided on a limited basis)

My opinions and conclusions as expressed in this report are based upon my education, training, work experience and general familiarity with supporting data in my areas of expertise, and the information provided to me by you, as well as my familiarity with the standards of practice of construction in the community. I have a Bachelor's of Science in Engineering Technology and Associate Degree in Construction Management Technology. I am a Certified Professional Estimator. Although my expertise is focused on estimating, I am often asked to give an opinion on scheduling, project phasing, constructability, site staging and market conditions as related to a particular project.

David Battle - FCPE, CERT





PRE CONSTRUCTION SERVICES, INC.

2512 W. INTERSTATE 44 SERVICE ROAD-OKLAHOMA CITY, OK 73112 VOICE: 405.722.5800 FAX: 405.602.3863 www.preconstructionservices.com

COST ESTIMATE SUMMARY

PROJECT: SMITH RESIDENCE
LOCATION: 314 EAST 8TH STREET CUSHING, OKLAHOMA
PREPARED FOR: CUSHING HOSPITALITY, LLC

PREPARED FOR: CUSHING HOSPITALITY, LL
ESTIMATE #: 18-026
ESTIMATOR: Pre Construction Services,

AATOR: Pre Construction Services, Inc. 8/22/2018

\$ 8,523

ESTIMATE TOTAL

8,523

TOTAL

SEE ATTACHED ESTIMATE - BREAKDOWN

PRE CONSTRUCTION SERVICES, INC.

SERVICES, INC NTERSTATE 44 SERVICE ROAD SITY, OK. 73112	UCTION SERVICES, INC 2512 W. INTERSTATE 44 SERVICE ROAD AHOMA CITY, OK. 73112 V: 405,722.5800 F: 405,602.3883	ONSTRUCTION SERVICES, INC 2512 W. INTERSTATE 44 SERVICE ROAD OKLAHOMA CITY, OK. 73112 V: 405,722.5800 F: 405,602.3883
	UCTION 2512 W. I	2512 W. I

SMITH RESIDENCE 314 E. 8TH CUSHING, OKLAHOMA

The part of the				KEP	N E	KEPAIK ESIIMAIE	щ								DATE:	8/22/2018	
SERVICES NO. FLOOR COST FLOOR COST FLOOR COST TOTAL TOTAL COST TOTAL TOTAL COST TOTAL TOTAL COST TOTAL TOTAL COST TOTAL TOTAL TOTAL COST TOTAL	DESCRIPTION: FORENSIC COST ESTIMATE				UNITC	STING E	ASED ON							Ĭ 	览	1,439	
FLOOR FOOT FLOOR FOOT FLOOR	LOCATION: 314 EAST 8TH ST. CUSHING, OK				RS ME	INS RESI	DENTIAL COS	STS 2018 37	TH ANNUA	EDITION							
FLORE FLOR	ESTIMATOR: PRE CONSTRUCTION SERVICES, INC.																
AREA FISAG SIGODE NAMERES OTT LOTAL COST TOTAL TOTAL COST TOTAL TOTAL COST TOTAL TOTAL COST TOTAL COST TOTAL COST TOTAL COST TOTA			COST	E	S MEANS	T	-		FERIAL	3	BOR	EQU	IPMENT	I ∩ ⊨	NTRACT		
MICHONA 1,439 SF 0,819 0,520 0,540 179 57 0,540 0,540 179 57 0,540 0,540 179 57 0,540 0,	DESCRIPTION A	AREA	FTSO	CSICO	DE NOM	BERS	-1	_	TOTAL	COST	TOTAL	COST	TOTAL	_	TOTAL	COST	TOTAL
Particolomy 150 15	DEMOCITION	1,439 SF	0.83 PSF		ĺ												
PERMISSAY RECROMA PENNICSSAY RECROOM PENNICS	PULL BACK CARPET IN LIVING ROOM			9080		0480	421 SF	00'0		0.07					0		29,47
Feminoses-Living Room Sept. 18-16 7200 15-A 0.00 0 1127A 113 22-14 22 0.00 0 0 0 0 0 0 0 0	PULL BACK CARPET IN SW BEDROOM			9060		0480	179 SF	00'0		70.0					0		12.53
Particle Say Bedracourage 154 1546 1520 15A	DEMO-SAWCUT FLOOR OPENINGS-LIVING ROOM			0241		7200	Ā	00.0		112,74				00'0	٥		134,88
TITRION 2.14" X.2502" THICK-LIVING ROOM	DEMO-SAWCUT FLOOR OPENINGS-SW BEDROOM			0241		7200	47	0.0		112.74					٥		134.88
SCREW JACKS AND PLATES 0152 340 340 0152 340 34	DEMO-STRIP FLOORING INTERIOR 2-1/4" X 25/32" THICK- LIVING	ROOM		9005	$\overline{}$	3400	80 FR	0.0		3,42					0		27,36
SCHEW JACKS AND PLATES HELOOR FEDISTAL OOR FRAME HOOR FEDISTAL OOR FRAME 1,439 SF 1,310 PSF 1,1429 SF 0,016 Gase 175 F 12	DEMO-STRIP FLOORING INTERIOR 2-1/4" X 25/32" THICK- SW BEI	DROOM		9060		3400	BS FS	00.0		3.42					0		27.36
HELOOR PEDISTAL 1,419 SF 1,31 PSF 1	SHORING FLOOR BEAMS - SCREW JACKS AND PLATES			0154		2650	12 EA	3,87		26,53					0		364,80
Comparison	SALVAGE BRICKS AT EACH FLOOR PEDISTAL			0405		2060	12 LF	0.00		35.41					0		424
POPE FRAME 1,31 PSF 1,31 PS	REMOVE FRONT ENTRY DOOR			9080		0200	Ą	0.0		17.71					0		17,
1,439 SF	REMOVE FRONT ENTRY DOOR FRAME			9080	14.5	2200	A A	0.0		23,21					0		23.
SEAMS-SCREW JACKS AND PLATES 13.49 13.40 13.40 13.41 13.40	MASONRY	1,439 SF	1.31 PSF														
1.TKG" LAID REGULAR 1,4139 SF 0.06 PSF 12 20.10 SF 0.02 PSF 12 20.10 SF 0.02 PSF 14.139 SF 0.01 PSF 0.01 PSF 0.02 PSF 14.139 SF 0.01 PSF 0.02 PSF 14.139 SF 0.01 PSF 0.01 PSF 0.02 PSF 0.	16"X16" COLUMN SOLID			0421		0400	12 LF	0 0		143,25					0		1,719.
1.TKG"LAID REGULAR 1.439 SF 0.06 PSF 1.NCL JAMB AND BRICKMOLD 1.10CL JAMB AND BRICKMOLD 1.10CB	REMOVE SHORING FLOOR BEAMS - SCREW JACKS AND PLATES	S		0154		2650	12 EA	0.0		13.26					0		159.
Thick Laid Recollar 1,439 sf 0,44 psf 1,439 sf 1,439 s	ROUGH CARPENTRY	1,439 SF	0.06 PSF														
Comparison Figure Comp	SUBFLOOR WITH BOARDS 1"X6" LAID REGULAR			0616		0452	16 SF	3.44							0		90.
NOTFINISHED BRICKMOLD 1,439 SF 0,617 S2,10 S550 1 EA 167.13 167 37.14 6.62 0.00 0 0 0.00 0 0	JOORS	1,439 SF	0.44 PSF														
NOTFINISHED 1,439 SF 0.61 PSF 0.62 PSF 0.63 PSF 0.64 PSF 0.65 PSF 0.64 PSF 0.65 PSF	NEW FRONT METAL DOOR INCL JAMB AND BRICKMOLD			0817		3550	1EA	376.31						0.00	0		422,
NOTFINISHED 1,439 SF 0.61 PSF 0964 29.01 46 SF 7.12 114 6.53 104 0.00 0 0 0.00 0 0.00 0 0 0.00 0 0 0.00 0 0 0.00 0 0 0.00 0 0 0.00 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	DOOR FINISH HARDWARE			0871		0400	1EA	167.13		37.14					0		204.
NOT FINISHED 1,439 SF 0.61 PSF 0.65 1 PSF 0.61 H 0 F ST 0.61 H 0 F ST 0.62 H 0 F D D D D D D D D D D D D D D D D D D	INISHES																
FRAME FR	PATCH OAK 25/32"X2-1/4", NOT FINISHED	1,439 SF	0.61 PSF			4900	16 SF	7.12		6.53				00.0	0		218.
FRAME 1989 1470 070 1 EA 16.39 17 124.68 125 0.00 0 <t< td=""><td>FINISH WOOD FLOORS</td><td></td><td></td><td>1880</td><td></td><td>3400</td><td>16 SF</td><td>0.60</td><td></td><td>1,33</td><td></td><td></td><td></td><td></td><td>0</td><td></td><td>30.88</td></t<>	FINISH WOOD FLOORS			1880		3400	16 SF	0.60		1,33					0		30.88
AD/PROFIT & INSURANCE AD/PROFIT & INSURANCE SINGERING FIES Description of the food Sir and the food Sir a	PAINT FRONT DOOR AND FRAME			1860		0370	1EA	16.96		124.68					0		141.67
AD/PROFIT & INSURANCE 27,00% 3,834 44 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	RE-LAY CARPET			9968		1070	600 SF	0.00		0,00					0		480.00
AD/PROFIT & INSURANCE 27,00% GENCY 10,00% 10							=										
AD/PROFIT & INSURANCE 27,00% GENCY 10,00% SINEERING FEES 9,00%	SUB TOTALS:								785		3,834		44		0		4,664
27,00% 10,00% 9,00%	SENERAL CONDITIONS			20.00%		6	0.										933
10.00% 9.00%	CONTRACTOR OVERHEAD/PROFIT & INSURANCE			27.00%													1,511
%00°6	RESTORATION CONTINGENCY			10.00%													711
	ARCHITECTURAL & ENGINEERING FEES			8.00%													704